Support team India



To configure a repx file

- 1. Save the customized repx file to a desired location.
- 2. Go to RebarCAD > Configuration Centre > Configure Schedule Settings.



RebarCAD - Configuration Centre		
Bor ⁿ Configuration	Label Configuration – Configuration –	Configure
Range Configuration	Couplers Configuration,	Miscellaneous Configuration
Support Files	Clabal/Ceneral Configuration Ford Pinewalth Bare BarColour	Change Configuration
	Close	



Support team India



- 3. Choose the Reports tab
- •••• button under Bar Schedule report format to browse to the saved 4. Choose the location and choose the repx file.
- 5. Click **Apply** and then click **Close**.

📚 RebarCAD - Configure Settings
Configure Settings Choose your preferred product settings including your revision management preferences, preferred schedule format, units formatting, production system settings, and the design and contents of your printed reports. These settings can be saved in a configuration file which can be shared between several computers to maintain consistent standards.
General Schedule Issuing & Revision Localisation Release & Ordering Reports Estimate Bar schedule report format
Template C:\ProgramData\CADS\AutoCAD 2011\CAD Customise
Weight report format
I emplate Weight Report by All Scheduled Bars Customite
Weight summary format
Template Weight Summary by Type/Size Customise
Save Apply X Close 🦃 Help

Now the BBS report will be generated as required.